















Date: 03.10.15
Data Source: TNRIS, SSURGO, Bing

-  Shed
-  Primary Road
-  Stream, Intermittent
-  Pond/Tank
-  Property Boundary

 Branyon clay, 0 to 1 percent slopes (BrA)	 Heiden clay, 3 to 5 percent slopes (HeC)	 Houston Black clay, 1 to 3 percent slopes (HoB)
 Burleson gravelly clay, 0 to 1 percent slopes (ByA)	 Heiden clay, 3 to 5 percent slopes, eroded (HeC3)	 Houston Black gravelly clay, 3 to 5 percent slopes (HpC)
 Burleson gravelly clay, 1 to 3 percent slopes (ByB)	 Houston Black clay, 0 to 1 percent slopes (HoA)	 Tinn clay, frequently flooded (Tw)